90 Route Closure

(T48N, R10W, Sec. 8, 17 and 18)





No warranty is made by the Bureau of Land Management as to the accuracy, reliability, or completeness of these data. Original data were compiled from various sources.This information may not meet National Map Accuracy Standards. This project was developed through digital means and may be updated without notice.

t:giswork/transportation/Dry_Creek_EA/arcprojects/90_closure_route.mxd 11-30-2006